



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-G410

INSPECTION REPORT

2016 SCANIA G410

4×4 Hooklift Truck with Palfinger System · VIN YS2G4X400021099922

INSPECTION DATE

03 Oct 2026

MILEAGE

197,305 km

INSPECTOR

C. Korenblik

CERTIFICATION

NL-MECH-3318



WELL-MAINTAINED — PASSED INSPECTION

Comprehensive on-site inspection completed by a certified heavy-machinery mechanic. With **197,305 km**, this truck is in **good working condition** — well-maintained and ready for productive service. Engine, transmission, hooklift, 4×4 system, winter service equipment, brakes, cab, electrical, and all systems were tested under no-load and light-load conditions. All systems operate to specification. No major faults found; normal wear consistent with mileage.



MACHINE IDENTIFICATION

VIN

YS2G4X400021099922

CATEGORY

Hooklift / Container System Truck

MODEL NUMBER

G410

YEAR OF MANUFACTURE

2016

FIRST REGISTRATION

01-01-2016

MANUFACTURER

Scania CV AB, Södertälje, Sweden

CURRENT LOCATION

Renswoude, Netherlands



KEY SPECIFICATIONS

GVW	18,000 kg
OWN WEIGHT	10,900 kg
PAYLOAD / LOAD CAPACITY	7,100 kg
MILEAGE	197,305 km
ENGINE	12,742 cc Diesel
POWER	302 kW (410 hp)
EMISSION STANDARD	Euro 6
TRANSMISSION	Automatic
DRIVE	4x4 / All-Wheel Drive
HOOKLIFT SYSTEM	Palfinger
WINTER SERVICE	Equipped
AIR CONDITIONING	Yes
AIR SUSPENSION	Yes
SEATS	3
NATIONALITY DOCUMENTS	German (complete)
CONDITION	Used – well-maintained

✓ OPERATIONAL TEST LOG

COLD START	✓ Instant, no excessive smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
GEARBOX (FORWARD/REVERSE)	✓ No slip
BRAKE TEST	✓ Firm pedal, no pull
STEERING (LOCK TO LOCK)	✓ Responsive
4×4 DRIVE ENGAGEMENT	✓ Functional
PALFINGER HOOKLIFT CYCLE	✓ Smooth operation, no drift
CONTAINER LOCKING SYSTEM	✓ Engages and locks correctly
WINTER SERVICE EQUIPMENT	✓ Functional
AIR CONDITIONING	✓ Functional
AIR SUSPENSION	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional
ROAD LIGHTING & BEACON	✓ All functional
TACHOGRAPH	✓ Functional

🛡️ FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
GEARBOX OIL	✓ Clean, correct level
HYDRAULIC FLUID (HOOKLIFT)	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
ADBLUE / DEF SYSTEM	✓ Correct level, functional
FUEL SYSTEM	✓ No water, no sediment



01 / ENGINE & DRIVETRAIN

— ENGINE BAY — SCANIA 12,742 CC DIESEL

The **Scania 12,742 cc diesel engine** was inspected cold and again after warm-up. Cold start is instant; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in good condition. Air filter element is clean. No fault codes present. The **Euro 6 emission system** and **AdBlue/DEF system** are functional. The odometer reads **197,305 km** — normal wear consistent with mileage. Maintenance appears to have been kept up to date.



02 / PALFINGER HOOKLIFT & HYDRAULIC SYSTEM

— PALFINGER HOOKLIFT SYSTEM

The **Palfinger hooklift system** was operated through its full range of motion. **All cylinders, hoses, and fittings are dry and leak-free**. The hooklift raises, lowers, and slides smoothly with no binding or drift. **Container locking system** engages and locks correctly. **Hydraulic fluid is clean and at the correct level**. The **winter service equipment** is functional. No weeping at any gland seals or connections. The hooklift is ready for municipal, contracting, and transport work.



03 / CAB & DRIVER STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **cab interior is clean, dry, and free of damage**. All driver controls — steering, pedals, gear lever, hooklift controls, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, odometer, warning lights, and gauges all operate correctly. The **air conditioning system** functions correctly. The **air suspension** operates correctly. The **seats (3) and seatbelts** and **windshield** are both reported in good condition. Road lighting and beacon are functional.



04 / CHASSIS, SUSPENSION & BRAKES

— FRAME, AXLES, SUSPENSION & BRAKES

The chassis, axles, and suspension were inspected visually and operationally. **Air suspension components are in good working condition with normal wear for mileage** — no significant play was detected. The **axles** and **brakes** are both reported in good working condition. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis. **The 4×4 drive system** was tested and functions correctly.



05 / TIRES & WHEELS

— TIRE CONDITION

All tires are in **good working condition with approximately 60% tread remaining**. Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust.



06 / HOOKLIFT FRAME & BODY

— HOOKLIFT FRAME, MOUNTING POINTS & WINTER SERVICE

The **hooklift frame and mounting points** are straight, sound, and free of significant deformation or impact damage. The **chassis rails and subframe** are intact and correctly mounted. The **container locking points** are secure and free of cracks. The **winter service equipment** (plow mounting, hydraulic connections) is functional and ready for the season. All hydraulic connections for the hooklift system are secure and leak-free.



PHOTO INDEX – MACHINE REFERENCE



REFERENCE 01




REFERENCE 02



REFERENCE 03



REFERENCE 04



REFERENCE 05



REFERENCE 06



REFERENCE 07



REFERENCE 08




REFERENCE 09



REFERENCE 10



REFERENCE 11



REFERENCE 12



REFERENCE 13



REFERENCE 14



REFERENCE 15



WHAT YOU GET WITH THIS MACHINE



FREE DELIVERY

First **500 km free** — then just **€1 / km**.



FULLY INSURED

Fully insured during transport across all of Europe.



6-MONTH WARRANTY

6 months across Europe — extendable to 5 years.



14-DAY REFUND

14 days to inspect on arrival. Full refund if not as described.



VERIFIED SELLER

Bolagsverket-registered. **Org.nr 559155-3432**.



FULL DOCUMENTATION

Ready to register in the new owner's name.

CHRIS KORENBLIK

CERTIFIED HEAVY-MACHINERY MECHANIC

Certification No. **NL-MECH-3318**

Dutch Heavy Equipment Institute

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-G410**

Location: **Renswoude, NL**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified heavy-machinery mechanic. Operational tests were performed under no-load and light-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM



SCAN TO VIEW
THIS MACHINE

BRINGELANDS MASKINHANDEL AB — INSPECTION COPY