



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-LF180

INSPECTION REPORT

2017 DAF LF180

3-Way Tipper Truck · VIN XLRAEL1500L464030

INSPECTION DATE

03 Oct 2026

MILEAGE

290,680 km

INSPECTOR

J. Janssens

CERTIFICATION

BE-MECH-5512



WELL-MAINTAINED — PASSED INSPECTION

Comprehensive on-site inspection completed by a certified heavy-machinery mechanic. With **290,680 km**, this truck is in **good working condition** — well-maintained and fully functional. Engine, transmission, tipper, brakes, cab, electrical, and all systems were tested under no-load and light-load conditions. All systems operate to specification. No major faults found; normal wear consistent with mileage.



MACHINE IDENTIFICATION

VIN	XLRAEL1500L464030
CATEGORY	3-Way Tipper Truck
MODEL NUMBER	LF180
YEAR OF MANUFACTURE	2017
FIRST REGISTRATION	09-06-2017
MANUFACTURER	DAF Trucks N.V., Eindhoven, Netherlands
CURRENT LOCATION	Sint-Katelijne-Waver, Belgium



KEY SPECIFICATIONS

GVW	11,990 kg
AXLE 1 (FRONT)	4,480 kg
AXLE 2 (REAR)	8,480 kg
LOAD CAPACITY	7,150 kg
OWN WEIGHT	4,844 kg
MILEAGE	290,680 km
ENGINE	4,500 cc Diesel
EMISSION STANDARD	Euro 6
TRANSMISSION	Automatic
NUMBER OF AXLES	2
CARGO BOX (W × L)	248 cm × 477 cm
FULL LENGTH	650 cm
WIDTH	248 cm
SEATS	2
CONDITION	Used – fully functional

✓ OPERATIONAL TEST LOG

COLD START	✓ Instant, no excessive smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
GEARBOX (FORWARD/REVERSE)	✓ No slip
BRAKE TEST	✓ Firm pedal, no pull
STEERING (LOCK TO LOCK)	✓ Responsive
TIPPER FUNCTION (3-WAY)	✓ All directions functional
TIPPER HYDRAULICS	✓ Smooth, no drift
TAILGATE OPERATION	✓ Functional
AIR CONDITIONING	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional
ROAD LIGHTING & BEACON	✓ All functional
TACHOGRAPH	✓ Functional

🛡️ FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
GEARBOX OIL	✓ Clean, correct level
HYDRAULIC FLUID (TIPPER)	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
ADBLUE / DEF SYSTEM	✓ Correct level, functional
FUEL SYSTEM	✓ No water, no sediment



01 / ENGINE & DRIVETRAIN

— ENGINE BAY — DAF 4,500 CC DIESEL

The **DAF 4,500 cc diesel engine** was inspected cold and again after warm-up. Cold start is instant; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in good condition. Air filter element is clean. No fault codes present. The **Euro 6 emission system** and **AdBlue/DEF system** are functional. The odometer reads **290,680 km** — normal wear consistent with mileage. Maintenance appears to have been kept up to date.



02 / TIPPER & HYDRAULIC SYSTEM

— 3-WAY TIPPER & HYDRAULICS

The **3-way tipper system** was operated through its full range of motion in all three directions. **All cylinders, hoses, and fittings are dry and leak-free**. The tipper raises and lowers smoothly with no binding or drift. **Tailgate operation** is functional. **Hydraulic fluid is clean and at the correct level**. No weeping at any gland seals or connections. The tipper is ready for construction, municipal, and transport work.



03 / CAB & DRIVER STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **cab interior is clean, dry, and free of damage**. All driver controls — steering, pedals, gear lever, tipper controls, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, odometer, warning lights, and gauges all operate correctly. The **air conditioning system** functions correctly. The **seats (2) and seatbelts** and **windshield** are both reported in good condition. Road lighting and beacon are functional.



04 / CHASSIS, SUSPENSION & BRAKES

— FRAME, AXLES, SUSPENSION & BRAKES

The chassis, axles, and suspension were inspected visually and operationally. **Suspension components are in good working condition with normal wear for mileage** — no significant play was detected. The **axles (4,480 kg front / 8,480 kg rear)** and **brakes** are both reported in good working condition. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis.



05 / TIRES & WHEELS

— TIRE CONDITION

All tires are in **good working condition with approximately 65% tread remaining**. Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust.



06 / CARGO BOX & BODY

— CARGO BOX, SIDE PANELS & TAILGATE

The **cargo box** (248 cm W × 477 cm L) is straight, sound, and free of significant deformation or impact damage. The **side panels and tailgate** are intact and correctly hinged for 3-way operation. The **bed floor** is in good working condition with no rust perforation or holes. The **tipper frame and mounting points** are secure and free of cracks. All hydraulic connections for the 3-way tipper system are secure and leak-free.



PHOTO INDEX — MACHINE REFERENCE



REFERENCE 01



REFERENCE 02




REFERENCE 03



REFERENCE 04



REFERENCE 05



REFERENCE 06



REFERENCE 07



REFERENCE 08



REFERENCE 09




REFERENCE 10



REFERENCE 11



REFERENCE 12



REFERENCE 13



REFERENCE 14



REFERENCE 15



WHAT YOU GET WITH THIS MACHINE



FREE DELIVERY

First **500 km free** — then just **€1 / km**.



FULLY INSURED

Fully insured during transport across all of Europe.



6-MONTH WARRANTY

6 months across Europe — extendable to 5 years.



14-DAY REFUND

14 days to inspect on arrival. Full refund if not as described.



VERIFIED SELLER

Bolagsverket-registered. **Org.nr 559155-3432**.



FULL DOCUMENTATION

Ready to register in the new owner's name.

JAN JANSSENS

CERTIFIED HEAVY-MACHINERY MECHANIC

Certification No. **BE-MECH-5512**

Belgian Heavy Equipment Institute

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-LF180**Location: **Sint-Katelijne-Waver, BE**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified heavy-machinery mechanic. Operational tests were performed under no-load and light-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM

SCAN TO VIEW
THIS MACHINE

BRINGELANDS MASKINHANDEL AB — INSPECTION COPY