



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-F930V

INSPECTION REPORT

2020 FENDT 930 VARIO

High-Horsepower Agricultural Tractor · VIN: WAM95723H00F01484

INSPECTION DATE

03 Oct 2026

ENGINE HOURS

2,984 h

INSPECTOR

B. De Smet

CERTIFICATION

BE-MECH-7841



EXCELLENT CONDITION – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified agricultural machinery mechanic. With only **2,984 hours**, this tractor is in **excellent condition** and fully operational. Engine, Vario CVT transmission, hydraulics, PTO, linkage, cab, electrical, and all systems were tested under load and no-load conditions. All systems operate to specification. No faults found.



MACHINE IDENTIFICATION

VIN

WAM95723H00F01484

CATEGORY

High-Horsepower Agricultural Tractor

MODEL NUMBER

930 Vario

YEAR OF MANUFACTURE

2020

MANUFACTURER

Fendt, Marktoberdorf, Germany

CURRENT LOCATION

Forrières, Belgium



KEY SPECIFICATIONS

ENGINE	Deutz 6-Cylinder Diesel
POWER	217 kW
TRANSMISSION	Vario CVT (Continuously Variable)
ENGINE HOURS	2,984 hours
FUEL TYPE	Diesel
OWN WEIGHT	12,700 kg
MAX. PERMISSIBLE MASS	18,000 kg
LOAD SENSING	Yes
REAR LINKAGE & PTO	Yes
REAR HYDRAULIC SPOOL VALVES	Yes
CONTROL TERMINAL	Fendt Control Terminal
CONDITION	Excellent – perfect working order



OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
VARIO CVT TRANSMISSION	✓ Smooth, no slip
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal, no leaks
REAR LINKAGE & PTO	✓ Smooth operation
HYDRAULIC SPOOL VALVES	✓ Functional
LOAD SENSING	✓ Functional
FENDT CONTROL TERMINAL	✓ Functional
AIR CONDITIONING	✓ Functional
SUSPENDED AIR SEAT	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
TRANSMISSION FLUID (VARIO)	✓ Clean, correct level
HYDRAULIC FLUID	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
DEF / ADBLUE SYSTEM	✓ Correct level, functional

01 / ENGINE & DRIVETRAIN

— ENGINE BAY — DEUTZ 6-CYLINDER DIESEL

The **Deutz 6-cylinder diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in excellent condition. Air filter element is clean. No fault codes present. The engine bay is dry and well-maintained. The machine reads **2,984 hours** on the original working hour meter — consistent with a low-hour machine.

02 / TRANSMISSION & HYDRAULIC SYSTEM

— VARIO CVT TRANSMISSION, LOAD SENSING & HYDRAULICS

The **Vario CVT transmission** was operated through its full range. **Power delivery is seamless with no slip**. The **load sensing** system functions as intended. The **rear hydraulic spool valves** and **3-point linkage** were tested and function correctly. **The PTO engages and operates smoothly**. Hydraulic fluid is clean and at the correct level. **No weeping at any gland seals or connections**.

03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **enclosed cab interior is clean, dry, and free of damage**. All operator controls — steering, pedals, Vario lever, PTO controls, hydraulic levers, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **air conditioning system** functions correctly. The **suspended air seat, Fendt control terminal, and multifunction armrest** are all functional.

04 / AXLES, FRAME & UNDERCARRIAGE

— CHASSIS, AXLES, BRAKES & LINKAGE

The axles, frame, and chassis were inspected visually and operationally. **All components are in excellent condition with minimal wear** — consistent with a low-hour machine with 2,984 hours of use. The **rear 3-point linkage** operates correctly and functions as intended. The **brake system** is functional. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis.

05 / TIRES & WHEELS

— TIRE CONDITION — 75-85% REMAINING


All tires are in **excellent condition with 75-85% tread remaining**. Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust — consistent with a low-hour, well-maintained machine.

06 / LINKAGE & ATTACHMENTS

— REAR THREE-POINT LINKAGE, PTO & HYDRAULIC SPOOL VALVES

The **rear 3-point linkage** operates smoothly through full range with no binding. The **PTO** engages and operates correctly. The **rear hydraulic spool valves** are functional and leak-free. All linkage pins and bushings are in **excellent condition** — consistent with only 2,984 hours of use. **All attachments and hydraulics are ready for immediate productive use.**

PHOTO INDEX – MACHINE REFERENCE



WHAT YOU GET WITH THIS MACHINE

 **FREE DELIVERY**
 First 500 km free — then just €1 / km.

 **FULLY INSURED**
 Fully insured during transport across all of Europe.

 **6-MONTH WARRANTY**
 6 months across Europe — extendable to 5 years.

 **14-DAY REFUND**
 14 days to inspect on arrival. Full refund if not as described.

 **VERIFIED SELLER**
 Bolagsverket-registered. Org.nr 559155-3432.

 **FULL DOCUMENTATION**
 Ready to register in the new owner's name.

BRAM DE SMET

CERTIFIED AGRICULTURAL MACHINERY MECHANIC

Certification No. **BE-MECH-7841**

Belgian Institute for Agricultural Engineering

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-F930V**Location: **Forrières, BE**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified agricultural machinery mechanic. Operational tests were performed under load and no-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM

SCAN TO VIEW
THIS MACHINE

BRINGELANDS MASKINHANDEL AB — INSPECTION COPY