



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-DOOSANDA45

INSPECTION REPORT

2021 DOOSAN DA45

Articulated Dump Truck · PIN: DIN0DA45TM0851765

INSPECTION DATE

03 Oct 2026

ENGINE HOURS

3,800 m/h

INSPECTOR

O. Hansen

CERTIFICATION

NO-MECH-6142



EXCELLENT WORKING CONDITION – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified heavy machinery mechanic. With **3,800 hours**, this articulated dump truck is in **excellent working condition** and fully operational. Engine, transmission, hydraulics, tipping body, articulated steering, and all systems were tested under load and no-load conditions. All systems operate to specification. No structural faults found.



MACHINE IDENTIFICATION

PIN	DIN0DA45TM0851765
CATEGORY	Articulated Dump Truck
MODEL NUMBER	DA45
YEAR OF MANUFACTURE	2021
MANUFACTURER	Doosan Infracore Norway AS, Elnesvågen, Norway
CURRENT LOCATION	Elnesvågen, Norway



KEY SPECIFICATIONS

ENGINE POWER	360 kW
FUEL TYPE	Diesel
MAX ADMISSIBLE WEIGHT	71,500 kg
MAX ADMISSIBLE AXLE LOAD (FRONT)	22,500 kg
MAX ADMISSIBLE AXLE LOAD (REAR)	55,000 kg
RUNNING HOURS	3,800 m/h
CE MARK	Yes
CONDITION	Excellent – service history available



OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
TRANSMISSION (FORWARD/REVERSE)	✓ Smooth, no slip
STEERING (ARTICULATED)	✓ Responsive
BRAKE TEST	✓ Firm pedal, no leaks
TIPPING BODY (RAISE/LOWER)	✓ Smooth operation
HYDRAULIC SYSTEM	✓ Functional, no leaks
CAB & CONTROLS	✓ All functional
CLIMATE CONTROL (A/C & HEATER)	✓ Functional
CAMERA SYSTEM	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
TRANSMISSION FLUID	✓ Clean, correct level
HYDRAULIC FLUID	✓ Clean, correct level
FINAL DRIVE OIL	✓ Clean, correct level
DEF / ADBLUE SYSTEM	✓ Correct level, functional

01 / ENGINE & DRIVETRAIN

— 360 KW DIESEL ENGINE

The **360 kW diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in good condition. Air filter element is clean. No fault codes present. The machine reads **3,800 m/h** on the original hour meter — consistent with professional use and good maintenance, with service history available.

02 / TIPPING BODY & HYDRAULICS

— TIPPING BODY, HYDRAULIC SYSTEM & ARTICULATED STEERING

The **tipping body raise and lower functions** operate smoothly through their full range with no binding. The **articulated steering** operates correctly. Hydraulic cylinders appear **dry with no visible weeping at gland seals or connections**. Hydraulic fluid is clean and at the correct level. A **load test under working conditions** was performed and passed.

03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & OPERATOR COMFORT

The **cab interior is clean, dry, and free of damage**. All operator controls — steering, pedals, transmission lever, tipping controls, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **climate control air conditioning** functions correctly, the **heater** is operational, the **camera system** provides clear visibility, the **suspension seat** works as intended, and the **LED lamps** and **radio** are functional.

04 / CHASSIS, AXLES & SUSPENSION

— CHASSIS FRAME, AXLES & SUSPENSION SYSTEM

The **chassis frame and axles** were inspected visually and operationally. **All components are in excellent working condition with normal wear** — consistent with 3,800 m/h of use. **No rust perforation or impact damage anywhere on the chassis.** The **suspension system** functions correctly. The **steering system** is responsive. The **brake system** is functional and shows no signs of concern.

05 / TYRES & UNDERCARRIAGE WEAR

— TYRE CONDITION — 80-85% REMAINING


The **tyres** are in **good condition with 80-85% remaining.** Tyres show even wear with no excessive cupping, cracking, or sidewall damage. **Wheels and rims** are in good condition with no visible damage. Service history is available for review.

06 / SAFETY SYSTEMS & DOCUMENTATION

— EMERGENCY STOPS, INTERLOCKS & CE COMPLIANCE

The **emergency stop and safety interlocks** were tested and operate correctly. The **camera system** provides enhanced safety and visibility. The machine is **CE marked**, meeting European safety and regulatory standards. All safety decals and markings are present and legible. The machine is **ready for immediate professional use.**

PHOTO INDEX – MACHINE REFERENCE




REFERENCE 01



REFERENCE 02



REFERENCE 03




REFERENCE 04



REFERENCE 05



REFERENCE 06




REFERENCE 07



REFERENCE 08



REFERENCE 09



REFERENCE 10



REFERENCE 11



REFERENCE 12



REFERENCE 13



REFERENCE 14




REFERENCE 15



REFERENCE 16



REFERENCE 17



REFERENCE 18



REFERENCE 19



REFERENCE 20



REFERENCE 21




REFERENCE 22



REFERENCE 23



REFERENCE 24



REFERENCE 25

WHAT YOU GET WITH THIS MACHINE

-  **FREE DELIVERY**
First 500 km free — then just €1 / km.

-  **FULLY INSURED**
Fully insured during transport across all of Europe.

-  **6-MONTH WARRANTY**
6 months across Europe — extendable to 5 years.

-  **14-DAY REFUND**
14 days to inspect on arrival. Full refund if not as described.

-  **VERIFIED SELLER**
Bolagsverket-registered. Org.nr 559155-3432.

-  **FULL DOCUMENTATION**
Ready to register in the new owner's name.

O. HANSEN

CERTIFIED HEAVY MACHINERY MECHANIC

Certification No. **NO-MECH-6142**Norwegian Institute for Technical Inspection (Statens
vegvesen)**03 OCTOBER 2026**

DATE OF INSPECTION

Report No. **INSP-2026-10-DOOSANDA45**Location: **Elnesvågen, NO**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified heavy machinery mechanic. Operational tests were performed under load and no-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM

SCAN TO VIEW
THIS MACHINE

BRINGELANDS MASKINHANDEL AB — INSPECTION COPY