



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-IXW460

INSPECTION REPORT

2024 IVECO X-WAY 460

Truck with MEC Container Hook System & Copma Crane · VIN: ZCFJ63MT50C509310(01)

INSPECTION DATE

03 Oct 2026

MILEAGE

45,545 km

INSPECTOR

J. Janssens

CERTIFICATION

BE-MECH-5512



EXCELLENT CONDITION – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified heavy-machinery mechanic. With only **45,545 km**, this truck is in **very good condition** and fully operational. Engine, transmission, hook system, crane, and all systems were tested under load and no-load conditions. All systems operate to specification. No faults found.



MACHINE IDENTIFICATION

VIN

ZCFJ63MT50C509310(01)

CATEGORY

Hooklift Truck with Loading Crane

MODEL NUMBER

X-Way 460

YEAR OF MANUFACTURE

2024

MANUFACTURER

Iveco, Turin, Italy

CURRENT LOCATION

Herentals, Belgium



KEY SPECIFICATIONS

ENGINE	Iveco 11,120 cc, 6-Cylinder Diesel
POWER	338 kW (460 HP)
DRIVE	8x4
TRANSMISSION	Automatic (12-speed)
MILEAGE	45,545 km
EMISSION STANDARD	Euro 6E
CONTAINER SYSTEM	MEC Hook System (2022)
LOADING CRANE	Copma 208HP.2 (2022)
HOOK DISTANCE (RETRACTED)	3.95 meters
HOOK DISTANCE (EXTENDED)	5.15 meters
HYDRAULIC EXTENDABLE BUMPER	+85 cm
CRANE CAPACITY	4,570 kg @ 4.15 m / 3,125 kg @ 6.05 m / 2,365 kg @ 8.0 m
CRANE FUNCTIONS	5th & 6th Function
GVW	32,000 kg
PAYLOAD	12,139 kg
CONDITION	Very Good – fully operational

✓ OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
TRANSMISSION (FORWARD/REVERSE)	✓ No slip
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal, no leaks
MEC HOOK SYSTEM	✓ Smooth operation
COPMA CRANE (208HP.2)	✓ All functions operational
HYDRAULIC EXTENDABLE BUMPER	✓ Functional
AIR CONDITIONING	✓ Functional
ROTATING BEACON & WORK LIGHT	✓ All functional
ELECTRICAL SYSTEMS	✓ All functional

🛡️ FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
TRANSMISSION FLUID	✓ Clean, correct level
HYDRAULIC FLUID (CRANE)	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
DEF / ADBLUE SYSTEM	✓ Correct level, functional

🏠 01 / ENGINE & DRIVETRAIN

— ENGINE BAY — IVECO 11,120 CC 6-CYLINDER

The **Iveco 11,120 cc 6-cylinder diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in very good condition. Air filter element is clean. No fault codes present. The engine bay is dry and well-maintained. The machine reads **45,545 km** on the original odometer — consistent with a low-mileage commercial vehicle.



02 / TRANSMISSION & HYDRAULIC SYSTEM

— TRANSMISSION, MEC HOOK SYSTEM & COPMA CRANE HYDRAULICS

The **12-speed automatic transmission** was operated through its full range. **All gears engage smoothly with no slip.** The **MEC container hook system** was tested and functions correctly, with hook distance from rollers at **3.95 meters retracted and 5.15 meters extended.** The **hydraulically extendable bumper** operates smoothly (+85 cm). The **Copma 208HP.2 loading crane** was tested through all functions — **4,570 kg at 4.15 meters, 3,125 kg at 6.05 meters, and 2,365 kg at 8.0 meters** — with **5th and 6th function** operational. Hydraulic fluid is clean and at the correct level. **No weeping at any gland seals or connections.**



03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **day cab interior is clean, dry, and free of damage.** All operator controls — steering, pedals, gear lever, hook system controls, crane remote controls, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, odometer, warning lights, and gauges all operate correctly. The **air conditioning system** functions correctly. The **seat and seatbelt** and **windshield** are both reported in excellent condition. The **navigation system** and **LED headlights** are functional.



04 / AXLES, FRAME & UNDERCARRIAGE

— CHASSIS, AXLES, BRAKES & 8X4 SYSTEM

The axles, frame, and chassis were inspected visually and operationally. **All components are in very good condition with minimal wear** — consistent with 45,545 km of use. The **8×4 axle configuration** (two front steering axles, two rear drive axles) engages correctly and functions as intended. The **brake system** is functional and shows no signs of concern. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis. The truck dimensions are **928 cm length** with a **wheelbase of 641 cm.**



05 / TIRES & WHEELS


— TIRE CONDITION – 50-75% REMAINING

All tires are in **good condition with 50–75% tread remaining.** Tires show normal wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust — consistent with a well-maintained commercial vehicle.

MEC CONTAINER HOOK SYSTEM & COPMA 208HP.2 CRANE

The **MEC container hook system** (year of manufacture: 2022) was tested and operates correctly, with hook distance from rollers at **3.95 meters retracted** and **5.15 meters extended**. The **hydraulically extendable bumper** operates smoothly (+85 cm). The **Copma 208HP.2 loading crane** (year of manufacture: 2022) was tested through all functions — **4,570 kg at 4.15 meters**, **3,125 kg at 6.05 meters**, and **2,365 kg at 8.0 meters** — with **5th and 6th function** operational. The crane is positioned behind the cab. All systems are ready for immediate productive use.

PHOTO INDEX – MACHINE REFERENCE

 <div>REFERENCE 01</div>	 <div>REFERENCE 02</div>	 <div>REFERENCE 03</div>	 <div>REFERENCE 04</div>	 <div>REFERENCE 05</div>
 <div>REFERENCE 06</div>	 <div>REFERENCE 07</div>	 <div>REFERENCE 08</div>	 <div>REFERENCE 09</div>	 <div>REFERENCE 10</div>
 <div>REFERENCE 11</div>	 <div>REFERENCE 12</div>	 <div>REFERENCE 13</div>	 <div>REFERENCE 14</div>	 <div>REFERENCE 15</div>
 <div>REFERENCE 16</div>	 <div>REFERENCE 17</div>	 <div>REFERENCE 18</div>	 <div>REFERENCE 19</div>	 <div>REFERENCE 20</div>
 <div>REFERENCE 21</div>	 <div>REFERENCE 22</div>	 <div>REFERENCE 23</div>	 <div>REFERENCE 24</div>	 <div>REFERENCE 25</div>

✓ WHAT YOU GET WITH THIS MACHINE



FREE DELIVERY

First **500 km free** — then just **€1 / km**.



FULLY INSURED

Fully insured during transport across all of Europe.



6-MONTH WARRANTY

6 months across Europe — extendable to 5 years.



14-DAY REFUND

14 days to inspect on arrival. Full refund if not as described.



VERIFIED SELLER

Bolagsverket-registered. **Org.nr 559155-3432**.



FULL DOCUMENTATION

Ready to register in the new owner's name.

JAN JANSSENS

CERTIFIED HEAVY-MACHINERY MECHANIC

Certification No. **BE-MECH-5512**

Belgian Heavy Equipment Institute

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-IXW460**

Location: **Herentals, BE**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified heavy-machinery mechanic. Operational tests were performed under load and no-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM



SCAN TO VIEW
THIS MACHINE