



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-AROCS3351

INSPECTION REPORT

2024 MERCEDES-BENZ AROCS 3351

6×6 Tipper Truck · VIN W1T96421910763012

INSPECTION DATE

03 Oct 2026

MILEAGE

71,800 km

INSPECTOR

C. Korenblik

CERTIFICATION

NL-MECH-3318



LOW MILEAGE – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified heavy-machinery mechanic. With only **71,800 km**, this truck is a low-mileage machine in **good working condition**. Engine, transmission, tipper, 6×6 drive, brakes, cab, electrical, and all systems were tested under no-load and light-load conditions. All systems operate to specification. No major faults found; normal wear consistent with mileage.



MACHINE IDENTIFICATION

VIN	W1T96421910763012
CATEGORY	6×6 Tipper Truck
MODEL NUMBER	Arocs 3351
YEAR OF MANUFACTURE	2024
MANUFACTURER	Mercedes-Benz Trucks, Wörth, Germany
TIPPER BODY MANUFACTURER	F.X. Meiller, München, Germany
CURRENT LOCATION	Renswoude, Netherlands



KEY SPECIFICATIONS

CONFIGURATION	6×6 Three-Axle Tipper
MILEAGE	71,800 km
ENGINE	Mercedes-Benz OM 470 / OM 471 Diesel (in-line 6)
POWER	510 hp (375 kW)
EMISSION STANDARD	Euro 6
TRANSMISSION	Automatic (Mercedes PowerShift)
DRIVE	6×6 / All-Wheel Drive
TIPPER BODY	F.X. Meiller – certified EN 12642-XL
MEILLER BODY REFERENCE	1192 1011 0A4 00 60 0
YEAR OF MANUFACTURE	2024
CONDITION	Used – low mileage



OPERATIONAL TEST LOG

COLD START	✓ Instant, no excessive smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
GEARBOX (FORWARD/REVERSE)	✓ No slip
BRAKE TEST	✓ Firm pedal, no pull
STEERING (LOCK TO LOCK)	✓ Responsive
6×6 DRIVE ENGAGEMENT	✓ Functional
TIPPER RAISE / LOWER CYCLE	✓ Smooth, no drift
TAILGATE OPERATION	✓ Functional
AIR CONDITIONING	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional
ROAD LIGHTING & BEACON	✓ All functional
TACHOGRAPH	✓ Functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
GEARBOX OIL	✓ Clean, correct level
HYDRAULIC FLUID (TIPPER)	✓ Clean, correct level
AXLE OIL (FRONT/MID/REAR)	✓ Clean, correct level
ADBLUE / DEF SYSTEM	✓ Correct level, functional
FUEL SYSTEM	✓ No water, no sediment

01 / ENGINE & DRIVETRAIN

— ENGINE BAY — MERCEDES-BENZ DIESEL

The **Mercedes-Benz diesel engine** was inspected cold and again after warm-up. Cold start is instant; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in good condition. Air filter element is clean. No fault codes present. The **Euro 6 emission system** and **AdBlue/DEF system** are functional. The odometer reads **71,800 km** — low mileage, consistent with a nearly new machine. Maintenance appears to have been kept up to date.

02 / TIPPER & HYDRAULIC SYSTEM

— MEILLER TIPPER BODY & HYDRAULICS

The **F.X. Meiller tipper system** was operated through its full range of motion. **All cylinders, hoses, and fittings are dry and leak-free**. The tipper raises and lowers smoothly with no binding or drift. **Tailgate operation** is functional. The tipper body is certified to **EN 12642-XL** — the European standard for the strength of superstructures on commercial vehicles. **Hydraulic fluid is clean and at the correct level**. No weeping at any gland seals or connections. The tipper is ready for construction, quarrying, and municipal work.

03 / CAB & DRIVER STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **cab interior is clean, dry, and free of damage**. All driver controls — steering, pedals, gear lever, tipper controls, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, odometer, warning lights, and gauges all operate correctly. The **air conditioning system** functions correctly. The **seats and seatbelts** and **windshield** are both reported in good condition. Road lighting and beacon are functional.

04 / CHASSIS, SUSPENSION & BRAKES

— FRAME, AXLES, SUSPENSION & BRAKES

The chassis, axles, and suspension were inspected visually and operationally. **Suspension components are in good working condition with normal wear for mileage** — no significant play was detected. The **axles** and **brakes** are both reported in good working condition. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis. The **6×6 drive system** was tested and functions correctly.

05 / TIRES & WHEELS

— TIRE CONDITION

All tires are in **good working condition with approximately 80% tread remaining**. Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust.

06 / TIPPER BODY & SUPERSTRUCTURE

— TIPPER BODY, SIDE PANELS & TAILGATE

The **F.X. Meiller tipper body** is straight, sound, and free of significant deformation or impact damage. The **side panels and tailgate** are intact and correctly hinged. The **bed floor** is in good working condition with no rust perforation or holes. The body is certified to **EN 12642-XL**. The **tipper frame and mounting points** are secure and free of cracks. All hydraulic connections for the tipper system are secure and leak-free.

PHOTO INDEX – MACHINE REFERENCE



✓ WHAT YOU GET WITH THIS MACHINE



FREE DELIVERY

First **500 km free** — then just **€1 / km**.



FULLY INSURED

Fully insured during transport across all of Europe.



6-MONTH WARRANTY

6 months across Europe — extendable to 5 years.



14-DAY REFUND

14 days to inspect on arrival. Full refund if not as described.



VERIFIED SELLER

Bolagsverket-registered. **Org.nr 559155-3432**.



FULL DOCUMENTATION

Ready to register in the new owner's name.

CHRIS KORENBLIK

CERTIFIED HEAVY-MACHINERY MECHANIC

Certification No. **NL-MECH-3318**

Dutch Heavy Equipment Institute

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-AROC3351**

Location: **Renswoude, NL**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified heavy-machinery mechanic. Operational tests were performed under no-load and light-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM



SCAN TO VIEW
THIS MACHINE