



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-NHT7315

INSPECTION REPORT

2016 NEW HOLLAND T7.315

High-Horsepower Agricultural Tractor 4WD · VIN: ZGEA02372

INSPECTION DATE

03 Oct 2026

ENGINE HOURS

2,131 h

INSPECTOR

B. De Smet

CERTIFICATION

BE-MECH-7841



EXCELLENT CONDITION – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified agricultural machinery mechanic. With **2,131 hours**, this tractor is in **excellent condition** and fully operational. Engine, transmission, hydraulics, PTO, linkage, cab, electrical, and all systems were tested under load and no-load conditions. All systems operate to specification. No faults found.



MACHINE IDENTIFICATION

VIN / SERIAL NO.

ZGEA02372

CATEGORY

High-Horsepower Agricultural Tractor (4WD)

MODEL NUMBER

T7.315

YEAR OF MANUFACTURE

2016

MANUFACTURER

New Holland Agriculture, Zedelgem, Belgium

CURRENT LOCATION

Aarschot, Belgium

KEY SPECIFICATIONS

ENGINE SIZE	6,728 cc
POWER	221 kW
TRANSMISSION	Automatic
DRIVE	4WD
ENGINE HOURS	2,131 hours
FUEL TYPE	Diesel
FRONT TIRES	650/60R34
REAR TIRES	710/75R42
FRONT LINKAGE	Yes
FIRST REGISTRATION	09/05/2016
CONDITION	Excellent – well maintained

OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
TRANSMISSION (FORWARD/REVERSE)	✓ Smooth, no slip
4WD ENGAGEMENT	✓ Functional
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal, no leaks
FRONT & REAR LINKAGE	✓ Smooth operation
PTO FUNCTION	✓ Correct operation
HYDRAULIC SPOOL VALVES	✓ Functional
CAB CONTROLS & INSTRUMENTATION	✓ All functional
ELECTRICAL SYSTEMS	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
TRANSMISSION FLUID	✓ Clean, correct level
HYDRAULIC FLUID	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
DEF / ADBLUE SYSTEM	✓ Correct level, functional

01 / ENGINE & DRIVETRAIN

— ENGINE BAY — 6,728 CC DIESEL

The **6,728 cc diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in excellent condition. Air filter element is clean. No fault codes present. The engine bay is dry and well-maintained. The machine reads **2,131 hours** on the original working hour meter — consistent with a low-hour machine.

02 / TRANSMISSION & HYDRAULIC SYSTEM

— AUTOMATIC TRANSMISSION, FRONT LINKAGE & HYDRAULICS

The **automatic transmission** was operated through its full range. **All gears engage smoothly with no slip**. The **4WD system** engages correctly and functions as intended. The **front linkage** and **rear 3-point linkage** operate smoothly through full range with no binding. The **rear hydraulic spool valves** were tested and function correctly. **The PTO engages and operates smoothly**. Hydraulic fluid is clean and at the correct level. **No weeping at any gland seals or connections**.

03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **enclosed cab interior is clean, dry, and free of damage**. All operator controls — steering, pedals, gear lever, PTO controls, hydraulic levers, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **seat and seatbelt** and **windshield** are all reported in excellent condition.

04 / AXLES, FRAME & UNDERCARRIAGE

— CHASSIS, AXLES, BRAKES & 4WD SYSTEM

The axles, frame, and chassis were inspected visually and operationally. **All components are in excellent condition with minimal wear** — consistent with 2,131 hours of use. The **4WD system** engages correctly and functions as intended. The **brake system** is functional. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis.

05 / TIRES & WHEELS

— TIRE CONDITION — 70-80% REMAINING


The large tires — **650/60R34 front** and **710/75R42 rear** — are in **good condition with 70-80% tread remaining**. Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust.

06 / LINKAGE & ATTACHMENTS

— FRONT LINKAGE, REAR 3-POINT LINKAGE & PTO

The **front linkage** and **rear 3-point linkage** operate smoothly through full range with no binding. The **PTO** engages and operates correctly. All linkage pins and bushings are in **excellent condition** — consistent with 2,131 hours of use. **All attachments and hydraulics are ready for immediate productive use.**

PHOTO INDEX – MACHINE REFERENCE



WHAT YOU GET WITH THIS MACHINE

 **FREE DELIVERY**
 First 500 km free — then just €1 / km.

 **FULLY INSURED**
 Fully insured during transport across all of Europe.

 **6-MONTH WARRANTY**
 6 months across Europe — extendable to 5 years.

 **14-DAY REFUND**
 14 days to inspect on arrival. Full refund if not as described.

 **VERIFIED SELLER**
 Bolagsverket-registered. Org.nr 559155-3432.

 **FULL DOCUMENTATION**
 Ready to register in the new owner's name.

BRAM DE SMET

CERTIFIED AGRICULTURAL MACHINERY MECHANIC

Certification No. **BE-MECH-7841**

Belgian Institute for Agricultural Engineering

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-NHT7315**Location: **Aarschot, BE**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified agricultural machinery mechanic. Operational tests were performed under load and no-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM



SCAN TO VIEW
THIS MACHINE

BRINGELANDS MASKINHANDEL AB — INSPECTION COPY