



INSPECTION REPORT

2020 CASE IH 75A 4WD

Utility Tractor · VIN: ELRFA75ALLAY00224

INSPECTION DATE

03 Oct 2026

ENGINE HOURS

400 h

INSPECTOR

A. Popescu

CERTIFICATION

RO-MECH-3392



EXCELLENT CONDITION – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified agricultural machinery mechanic. With only **400 working hours**, this tractor is in **excellent condition** and fully operational. Engine, transmission, hydraulics, PTO, linkage, cab, electrical, and all systems were tested under load and no-load conditions. All systems operate to specification. No faults found.



MACHINE IDENTIFICATION

VIN

ELRFA75ALLAY00224

CATEGORY

Utility Agricultural Tractor (4WD)

MODEL NUMBER

75A

YEAR OF MANUFACTURE

2020

MANUFACTURER

CNH Industrial Italia S.p.A. – Made in Turkey

CURRENT LOCATION

Sălaj, Romania

KEY SPECIFICATIONS

ENGINE	CNH Diesel
TRANSMISSION	Automatic
DRIVE	4WD
ENGINE HOURS	400 hours
FUEL TYPE	Diesel
OWN WEIGHT	4,800 kg
FRONT AXLE MAX	2,500 kg
REAR AXLE MAX	3,300 kg
CAB	Yes (enclosed)
EU TYPE APPROVAL	e13*167/2013*00168*
CONDITION	Excellent – exceptionally low-hour machine

OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
TRANSMISSION (FORWARD/REVERSE)	✓ Smooth, no slip
4WD ENGAGEMENT	✓ Functional
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal, no leaks
REAR LINKAGE	✓ Smooth operation
PTO FUNCTION	✓ Correct operation
HYDRAULIC SPOOL VALVES	✓ Functional
CAB CONTROLS & INSTRUMENTATION	✓ All functional
ELECTRICAL SYSTEMS	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
TRANSMISSION FLUID	✓ Clean, correct level
HYDRAULIC FLUID	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
FUEL SYSTEM	✓ No water, no sediment

01 / ENGINE & DRIVETRAIN

— ENGINE BAY — CNH DIESEL

The **CNH diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in excellent condition. Air filter element is clean. No fault codes present. The engine bay is dry and well-maintained. The machine reads **400 working hours** on the original hour meter — consistent with an exceptionally low-hour machine.

02 / TRANSMISSION & HYDRAULIC SYSTEM

— TRANSMISSION, REAR LINKAGE & HYDRAULICS

The **transmission** was operated through its full range. **All gears engage smoothly with no slip**. The **4WD system** engages correctly and functions as intended. The **rear hydraulic spool valves** and **3-point linkage** were tested and function correctly. **The PTO engages and operates smoothly**. Hydraulic fluid is clean and at the correct level. **No weeping at any gland seals or connections**.

03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **enclosed cab interior** is **clean, dry, and free of damage**. All operator controls — steering, pedals, gear lever, PTO controls, hydraulic levers, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **seat and seatbelt** and **windshield** are all reported in excellent condition.

04 / AXLES, FRAME & UNDERCARRIAGE

— CHASSIS, AXLES, BRAKES & 4WD SYSTEM

The axles, frame, and chassis were inspected visually and operationally. **All components are in excellent condition with minimal wear** — consistent with only 400 hours of use. The **4WD system** engages correctly and functions as intended. The **brake system** is functional. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis.

05 / TIRES & WHEELS

— TIRE CONDITION — 90-95% REMAINING

All four tires are in **excellent condition with 90-95% tread remaining**. Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust — consistent with an exceptionally low-hour machine.

06 / LINKAGE & ATTACHMENTS


— REAR 3-POINT LINKAGE, PTO & HYDRAULIC SPOOL VALVES

The **rear 3-point linkage** operates smoothly through full range with no binding. The **PTO** engages and operates correctly. The **rear hydraulic spool valves** are functional and leak-free. All linkage pins and bushings are in **excellent condition** — consistent with only 400 hours of use. **All attachments and hydraulics are ready for immediate productive use.**


07 / PHOTO INDEX — MACHINE REFERENCE



REFERENCE 01



REFERENCE 02



REFERENCE 03




REFERENCE 04




REFERENCE 05



REFERENCE 06




REFERENCE 07




REFERENCE 08



REFERENCE 09



REFERENCE 10



REFERENCE 11



REFERENCE 12



REFERENCE 13



REFERENCE 14



REFERENCE 15

✓ WHAT YOU GET WITH THIS MACHINE



FREE DELIVERY

First **500 km free** — then just **€1 / km**.



FULLY INSURED

Fully insured during transport across all of Europe.



6-MONTH WARRANTY

6 months across Europe — extendable to 5 years.



14-DAY REFUND

14 days to inspect on arrival. Full refund if not as described.



VERIFIED SELLER

Bolagsverket-registered. **Org.nr 559155-3432**.



FULL DOCUMENTATION

Ready to register in the new owner's name.

ANDREI POPESCU

CERTIFIED AGRICULTURAL MACHINERY MECHANIC

Certification No. **RO-MECH-3392**

Romanian Institute for Agricultural Machinery

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-CIH75A**

Location: **Sălaj, RO**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified agricultural machinery mechanic. Operational tests were performed under load and no-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM



SCAN TO VIEW
THIS MACHINE