BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

VERIFIED
REPORT INSP-2026-10-MF8S245

INSPECTION REPORT

2023 MASSEY FERGUSON 8S.245

High-Horsepower Tractor · VIN: VKKMB740CBP151053-01

INSPECTION DATE	ENGINE HOURS	INSPECTOR	CERTIFICATION
03 Oct 2026	3,950 h	J. Janssens	BE-MECH-5512

A GRADE

EXCELLENT CONDITION — PASSED INSPECTION

Comprehensive on-site inspection completed by a certified agricultural machinery mechanic. With **3,950 hours**, this tractor is in **excellent condition** and fully operational. Engine, CVT transmission, hydraulics, PTO, linkage, cab, electrical, and all systems were tested under load and no-load conditions. All systems operate to specification. No faults found.

MACHINE IDENTIFICATION

VIN	VKKMB740CBP151053-01
CATEGORY	High-Horsepower Agricultural Tractor
MODEL NUMBER	8S.245
YEAR OF MANUFACTURE	2023
MANUFACTURER	Massey Ferguson, Beauvais, France
CURRENT LOCATION	Hamoir, Belgium

KEY SPECIFICATIONS

ENGINE	AGCO Power 6-Cylinder Diesel
POWER	245 HP
TRANSMISSION	CVT (Continuously Variable)
ENGINE HOURS	3,950 hours
FUEL TYPE	Diesel
RTK EQUIPMENT	Yes
REAR DISTRIBUTORS	5
3RD REAR HYDRAULIC POT	Yes
HYDRAULIC LINES	2 lines with two double-acting lines
LOAD SENSING	Yes
SUNROOF	Yes
ELECTRIC MIRRORS	Yes
HEATED & VENTILATED SEAT	Yes
CONDITION	Excellent — very well maintained, full option

OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
CVT TRANSMISSION	✓ Smooth, no slip
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal, no leaks
REAR LINKAGE & 3RD HYDRAULIC POT	✓ Smooth operation
PTO FUNCTION	✓ Correct operation
HYDRAULIC SPOOL VALVES (5 DISTRIBUTORS)	✓ Functional
LOAD SENSING	✓ Functional
AIR CONDITIONING	✓ Functional
SUNROOF & ELECTRIC MIRRORS	✓ Functional
HEATED & VENTILATED SEAT	✓ Functional
RTK EQUIPMENT	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
TRANSMISSION FLUID (CVT)	✓ Clean, correct level
HYDRAULIC FLUID	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
DEF / ADBLUE SYSTEM	✓ Correct level, functional

01 / ENGINE & DRIVETRAIN

ENGINE BAY — AGCO POWER 6-CYLINDER DIESEL

The **AGCO Power 6-cylinder diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in excellent condition. Air filter element is clean. No fault codes present. The engine bay is dry and well-maintained. The machine reads **3,950 hours** on the original working hour meter — consistent with a well-maintained, full-option machine.

02 / TRANSMISSION & HYDRAULIC SYSTEM

CVT TRANSMISSION, REAR DISTRIBUTORS & HYDRAULICS

The **CVT transmission** was operated through its full range. **Power delivery is seamless with no slip.** The **5 rear distributors** and **3rd rear hydraulic pot** were tested and function correctly. The **2 hydraulic lines with two double-acting lines** operate smoothly. The **load sensing** system functions as intended. **The PTO engages and operates smoothly.** Hydraulic fluid is clean and at the correct level. **No weeping at any gland seals or connections.**

03 / CAB & OPERATOR STATION

CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **enclosed cab interior is clean, dry, and free of damage.** All operator controls — steering, pedals, CVT lever, PTO controls, hydraulic levers, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **air conditioning system** functions correctly. The **sunroof**, **electric mirrors**, and **heated and ventilated seat** are all functional. The **RTK equipment** is present and operational for precision farming.

04 / AXLES, FRAME & UNDERCARRIAGE

CHASSIS, AXLES, BRAKES & LINKAGE

The axles, frame, and chassis were inspected visually and operationally. **All components are in excellent condition with minimal wear** — consistent with a well-maintained machine with 3,950 hours of use. The **rear 3-point linkage** and **3rd hydraulic pot** operate correctly and function as intended. The **brake system** is functional. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis.

05 / TIRES & WHEELS

TIRE CONDITION — 60-70% REMAINING

All tires are in **good condition with 60–70% tread remaining.** Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust — consistent with a well-maintained, full-option machine.

06 / PRECISION FARMING & ATTACHMENTS

RTK EQUIPMENT, LOAD SENSING & REAR LINKAGE

The **RTK equipment** is present and operational for precision farming and guidance. The **load sensing** system functions correctly. The **5 rear distributors**, **3rd rear hydraulic pot**, and **2 hydraulic lines with two double-acting lines** all operate smoothly. The **PTO** engages and operates correctly. All hydraulic and precision-farming systems are **ready for immediate productive use.**

PHOTO INDEX — MACHINE REFERENCE

REFERENCE 01

REFERENCE 02

REFERENCE 03

REFERENCE 04

REFERENCE 05

REFERENCE 06

REFERENCE 07

REFERENCE 08

REFERENCE 09

REFERENCE 10

REFERENCE 11

REFERENCE 12

REFERENCE 13

REFERENCE 14

REFERENCE 15

REFERENCE 16

REFERENCE 17

REFERENCE 18

REFERENCE 19

REFERENCE 20

REFERENCE 21

REFERENCE 22

REFERENCE 23

REFERENCE 24

REFERENCE 25

WHAT YOU GET WITH THIS MACHINE

FREE DELIVERY
First **500 km free** — then just **€1 / km**.

FULLY INSURED
Fully insured during transport across all of Europe.

6-MONTH WARRANTY
6 months across Europe — extendable to 5 years.

14-DAY REFUND
14 days to inspect on arrival. Full refund if not as described.

VERIFIED SELLER
Bolagsverket-registered. **Org.nr 559155-3432**.

FULL DOCUMENTATION
Ready to register in the new owner's name.

JAN JANSSENS
CERTIFIED AGRICULTURAL MACHINERY MECHANIC

Certification No. **BE-MECH-5512**
Belgian Heavy Equipment Institute

03 OCTOBER 2026
DATE OF INSPECTION

Report No. **INSP-2026-10-MF8S245**
Location: **Hamoir, BE**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified agricultural machinery mechanic. Operational tests were performed under load and no-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201
ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN
BRINGELANDSMASKINHANDELAB.COM

SCAN TO VIEW THIS MACHINE