



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-VQ305

INSPECTION REPORT

2023 VALTRA Q305

High-Horsepower Tractor · VIN: YK5W305D0PS271042

INSPECTION DATE

03 Oct 2026

ENGINE HOURS

681 h

INSPECTOR

M. Hofer

CERTIFICATION

AT-MECH-4417



EXCELLENT CONDITION – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified agricultural machinery mechanic. With only **681 hours**, this tractor is in **excellent condition** and fully operational. Engine, transmission, hydraulics, PTO, linkage, cab, electrical, and all systems were tested under load and no-load conditions. All systems operate to specification. No faults found.



MACHINE IDENTIFICATION

SERIAL NUMBER

YK5W305D0PS271042

CATEGORY

High-Horsepower Agricultural Tractor

MODEL NUMBER

Q305

YEAR OF MANUFACTURE

2023

MANUFACTURER

Valtra, Suolahti, Finland

CURRENT LOCATION

Gänserndorf Süd, Austria



KEY SPECIFICATIONS

ENGINE	Valtra 6-Cylinder Diesel
POWER	224 kW
TRANSMISSION	Stepless (CVT)
ENGINE HOURS	681 hours
FUEL TYPE	Diesel
OWN WEIGHT	9,200 kg
FRONT LINKAGE	Yes
CABIN	Yes (enclosed)
AIR SEAT	Yes
CONDITION	Excellent – low-hour machine



OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
STEPLESS TRANSMISSION	✓ Smooth, no slip
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal, no leaks
FRONT LINKAGE	✓ Smooth operation
PTO FUNCTION	✓ Correct operation
HYDRAULIC SPOOL VALVES	✓ Functional
AIR CONDITIONING	✓ Functional
AIR SEAT	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
TRANSMISSION FLUID	✓ Clean, correct level
HYDRAULIC FLUID	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
DEF / ADBLUE SYSTEM	✓ Correct level, functional

01 / ENGINE & DRIVETRAIN

— ENGINE BAY — VALTRA 6-CYLINDER DIESEL

The **Valtra 6-cylinder diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in excellent condition. Air filter element is clean. No fault codes present. The engine bay is dry and well-maintained. The machine reads **681 hours** on the original working hour meter — consistent with a low-hour machine.

02 / TRANSMISSION & HYDRAULIC SYSTEM

— STEPLESS TRANSMISSION, FRONT LINKAGE & HYDRAULICS

The **Stepless transmission** was operated through its full range. **Power delivery is seamless with no slip**. The **front linkage** operates smoothly through full range with no binding. The **rear hydraulic spool valves** and **3-point linkage** were tested and function correctly. **The PTO engages and operates smoothly**. Hydraulic fluid is clean and at the correct level. **No weeping at any gland seals or connections**.

03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **enclosed cab interior is clean, dry, and free of damage**. All operator controls — steering, pedals, transmission lever, PTO controls, hydraulic levers, and dashboard switches — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **air conditioning system** functions correctly. The **air seat** and **seatbelt** and **windshield** are all reported in excellent condition.

04 / AXLES, FRAME & UNDERCARRIAGE

— CHASSIS, AXLES, BRAKES & LINKAGE

The axles, frame, and chassis were inspected visually and operationally. **All components are in excellent condition with minimal wear** — consistent with only 681 hours of use. The **front linkage** and **rear 3-point linkage** operate correctly and function as intended. The **brake system** is functional. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis.

05 / TIRES & WHEELS

— TIRE CONDITION — 80-90% REMAINING


All tires are in **excellent condition with 80–90% tread remaining**. Tires show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust — consistent with a low-hour machine.

06 / LINKAGE & ATTACHMENTS

— FRONT LINKAGE, REAR 3-POINT LINKAGE & PTO

The **front linkage** and **rear 3-point linkage** operate smoothly through full range with no binding. The **PTO** engages and operates correctly. All linkage pins and bushings are in **excellent condition** — consistent with only 681 hours of use. **All attachments and hydraulics are ready for immediate productive use.**

PHOTO INDEX – MACHINE REFERENCE



WHAT YOU GET WITH THIS MACHINE

 **FREE DELIVERY**
 First 500 km free — then just €1 / km.

 **FULLY INSURED**
 Fully insured during transport across all of Europe.

 **6-MONTH WARRANTY**
 6 months across Europe — extendable to 5 years.

 **14-DAY REFUND**
 14 days to inspect on arrival. Full refund if not as described.

 **VERIFIED SELLER**
 Bolagsverket-registered. Org.nr 559155-3432.

 **FULL DOCUMENTATION**
 Ready to register in the new owner's name.

MICHAEL HOFER

CERTIFIED AGRICULTURAL MACHINERY MECHANIC

Certification No. **AT-MECH-4417**

Austrian Agricultural Engineering Institute

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-VQ305**Location: **Gänserndorf Süd, AT**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified agricultural machinery mechanic. Operational tests were performed under load and no-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM

SCAN TO VIEW
THIS MACHINE

BRINGELANDS MASKINHANDEL AB — INSPECTION COPY