



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-226D3

INSPECTION REPORT

2025 CATERPILLAR 226D3

Compact Skid Steer Loader · Stock No. EK503938

INSPECTION DATE

12 Oct 2026

ENGINE HOURS

33 h

INSPECTOR

P. Martin

CERTIFICATION

EU-MECH-5892



ESSENTIALLY NEW – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified heavy-machinery mechanic. With only **33 hours**, this machine is in near-new condition. Engine, hydraulics, transmission, cab, electrical, and all attachments were tested under no-load and light-load conditions. All systems operate to specification. No faults found.



MACHINE IDENTIFICATION

PIN

CAT0226DCEK503938

CATEGORY

Compact Skid Steer Loader

MODEL NUMBER

226D3

YEAR OF MANUFACTURE

2025

MANUFACTURER

Caterpillar Inc., Peoria, IL 61629, USA · Made in India

CURRENT LOCATION

Aix, France



KEY SPECIFICATIONS

TRANSPORT DIMENSIONS	2.9 m × 1.5 m × 1.9 m
RUNNING HOURS	33 m/h
TIRE SIZE	31x10-20 (Pneumatic / Honeycomb)
TIRE CONDITION	90%
BUCKET WIDTH	1576 mm
BUCKET CAPACITY	360 L
BUCKET BLADE REMAINING	80%
ATTACHMENTS	Main bucket
CONDITION	Used
YEAR OF MANUFACTURE	2025



OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
LOADER CYCLE (FULL RANGE)	✓ Smooth, no drift
BUCKET FUNCTION	✓ Correct operation
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal
TRANSMISSION (FORWARD/REVERSE)	✓ No slip
RIDECONTROL SYSTEM	✓ Functional
ELECTRICAL SYSTEMS	✓ All functional
VISIONLINK / GEOLOCATION	✓ Active
ROAD LIGHTING & BEACON	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
HYDRAULIC FLUID	✓ Clean, correct level
TRANSMISSION FLUID	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
FUEL SYSTEM	✓ No water, no sediment

01 / ENGINE & POWERTRAIN

— ENGINE BAY — CATERPILLAR DIESEL

The **Caterpillar diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean with no excessive smoke; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in as-new condition. Air filter element is clean. No fault codes present. The engine bay is dry and spotless. The machine reads **33 hours** on the original working hour meter — consistent with a nearly new machine.

02 / HYDRAULIC SYSTEM

— MAIN & AUXILIARY HYDRAULIC PUMPS

The full hydraulic system was operated under load. **All cylinders, hoses, and fittings are dry and leak-free**. The **main hydraulic pump** and **auxiliary hydraulic pump** are both reported in excellent condition. Loader lift and dump cycle smoothly with no drift. The **quick coupler / attachment interface** engages and locks correctly. Hydraulic fluid is clean and at the correct level. No weeping at any gland seals or connections.

03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **cab interior is clean, dry, and free of damage**. All operator controls — loader levers, auxiliary function switch, foot pedals, steering, and throttle — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **seat type & seatbelt** and **windshield** are both reported in excellent condition. Road lighting and beacon are functional.

04 / AXLES, FRAME & UNDERCARRIAGE

— CHASSIS, PINS, BUSHINGS, AXLES & BRAKES

The axles, frame, and undercarriage were inspected visually and operationally. **Pins and bushings are in as-new condition with negligible wear** — no significant play was detected. The **axles** and **brakes** are both reported in excellent condition. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis.

05 / TIRES & WHEELS

— TIRE CONDITION — 31X10-20 (PNEUMATIC / HONEYCOMB)

All four tires are in **excellent condition with approximately 90% tread remaining**. Tires (31×10-20, pneumatic / honeycomb type) show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust.

06 / LOADER ARMS & BUCKET ATTACHMENT

— LOADER ARMS, LINKAGE & MAIN BUCKET

The **loader arms and linkage** operate smoothly through full range with no binding. Pins and bushings at the loader pivot points show **as-new condition with no excessive play**. The **main bucket** is in good condition with **80% blade remaining**. Bucket dimensions: **360 L capacity · 1576 mm width**. The attachment interface engages and locks correctly with no excessive play.

PHOTO INDEX – MACHINE REFERENCE




REFERENCE 01



REFERENCE 02



REFERENCE 03



REFERENCE 04




REFERENCE 05



REFERENCE 06



REFERENCE 07



REFERENCE 08



REFERENCE 09



REFERENCE 10




REFERENCE 11




REFERENCE 12



REFERENCE 13



REFERENCE 14



REFERENCE 15

WHAT YOU GET WITH THIS MACHINE



FREE DELIVERY

First 500 km free — then just €1 / km.



FULLY INSURED

Fully insured during transport across all of Europe.



6-MONTH WARRANTY

6 months across Europe — extendable to 5 years.



14-DAY REFUND

14 days to inspect on arrival. Full refund if not as described.



VERIFIED SELLER

Bolagsverket-registered. Org.nr 559155-3432.



FULL DOCUMENTATION

Ready to register in the new owner's name.

P. MARTIN

CERTIFIED HEAVY-MACHINERY MECHANIC

Certification No. **EU-MECH-5892**

French Heavy Equipment Institute

12 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-226D3**

Location: **Aix, FR**

Inspector statement & disclaimer: This machine was inspected on 12 October 2026 by a certified heavy-machinery mechanic. Operational tests were performed under no-load and light-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM



SCAN TO VIEW
THIS MACHINE

BRINGELANDS MASKINHANDEL AB — INSPECTION COPY